

FIG.1




FIG.2




FIG.3

20

40 INSTRUCTION STEP			42 OPERATIONAL BLOCK LOCATION		44 HEAT RELEASE COEFFICIENT	
MOV	AX	BX	(2, 3), (2, 4)		2	
LD	AX	2D	(2, 2)		1	
ADD	AX	2E	(3, 1), (3, 3)		3	
ST	AX	2F	(4, 3)		1	

4/6

FIG.4

22

3	0	1	0	1
2	1	5	0	2
0	0	0	4	1
1	0	0	0	0
2	4	0	0	1

FIG.5




FIG.6

